





1 First National Bank ALASKA—
A genuine interest in the success of Alaskans.



1 First National Bank ALASKA—
A genuine interest in the success of Alaskans.



Seven shelter windows (in progress) replaced
per commercial building inspection recommendation



Commercial Kitchen stove, but no fire suppression hood as required by (self-requested) OSHA inspection '05. Confirmed as a fire hazard/unsafe condition in the shelter.




First National Bank ALASKA
A genuine interest in the success of Alaskans.

View of front reception area and front outside entry.
Note: No video monitor for receptionist, and front door open without first clearing access/security.
(Reception area hallway leads directly into shelter.)



First National Bank ALASKA —
A genuine interest in the success of business.



Physician's Table (note duct tape):



First National Bank ALASKA
A genuine interest in the success of Alaskans.



First National Bank ALASKA
A genuine interest in the success of Alaskans.



Seven shelter windows (in progress) replaced
per commercial building inspection recommendations



① **First National Bank ALASKA** —  *A genuine interest in the success of Alaskans.*

View of front reception area and front outside entry.
Note: No video monitor for receptionist, and front door open without first clearing access/security.
(Reception area hallway leads directly into shelter.)



Commercial Kitchen stove, but no fire suppression hood as required by (self-requested) OSHA inspection '05. Confirmed as a fire hazard/unsafe condition in the shelter.



First National Bank ALASKA
A genuine interest in the success of Alaskans.



Physician's Table (note duct tape):