



1. ESTABLISH SELF USE GUIDELINES OR REGULATE USE.
2. ESTABLISH REGULAR HOURS OF OPERATION.
3. BURY ALL EXISTING PLASTICS AND NONBURNABLE ITEMS TO PIT #1 AND COVER.
4. SMOOTH COVER AND COMPACT TO FORM PAD FOR METALS RECYCLING.
5. INSTALL GATE FOR SITE CONTROL AFTER CLEANUP.

REMOVE EXISTING PLASTIC TO PROPOSED BURIAL PIT#1 THEN EXCAVATE NEW BURNABLE PIT.

**FIGURE**

DATE: 8/14/06  
 DRAFTER: DDR  
 CHECKED BY: DL  
 SCALE: N.T.S.

**CITY OF FALSE PASS  
 LANDFILL RECOMMENDATIONS**

