


F4




Boiler Room Floor, Plywood




ALSO BLUE prints show 3 Boilers  
and 2 Hot water Heaters.  
There Are only 2 Boilers AND 1 water Heater.

F5



- ① only one sink and  
one toilet per rest room.  
blue prints shows two  
each toilets & sinks
- ② walls not done.
- ③ floors not done.

F6



2 EA. Broken windows, installed that way



- ① Building weathered, finish gone
- ② Fuel Tank on wooded stand  
And hooked up in proper and lenks.

F7




ARCTIC ENTRY too SMALL AND  
steps going the wrong WAY, Also too step.





F8



washers & dryers



F9



NEVER Hooked up