URS

Photographs of URS Site Visit to Seward Rail Dock February 28, 2010

Z Float Modules barge unloading.

Z Float module moving on truck

Z Float Modules upland yard unloading.



Z Float Modules upland yard stacking.

URS

Z Float Modules upland yard rows

Z Float Modules minor damage to Z-12 stringer



Z Float Modules minor damage to Z-12 stringer

Aluminum gangway