

# CONSTRUCTION INSPECTION REPORT

<b>Project: Knudson Cove Harbor</b>	<b>Report No: KCH 01</b>
<b>File No : 062010.05</b>	<b>Date: January 21, 2009</b>
<b>Consultant: PND Engineers, Inc.</b>	<b>Day of the Week: Wednesday</b>

<b>WEATHER</b>	Bright Sun	Clear <input checked="" type="checkbox"/>	Overcast	Rain	Snow	Other
<b>TEMP</b>	Below 0	0-32 <input checked="" type="checkbox"/>	32-50	50-70	70-85	Over 85
<b>WIND</b>	Still <input checked="" type="checkbox"/>	Mod	High	<b>Comments:</b>		
<b>HUMIDITY</b>	Dry	Mod <input checked="" type="checkbox"/>	Humid	<b>Comments:</b>		

<u>Name of Contractor</u>	<u>Non-Manual</u>	<u>Manual</u>	<u>Remarks</u>
Pool Engineer		5	

**CONTACTS**

<u>Name</u>	<u>Title</u>	<u>Phone No.</u>	<u>Remarks</u>
Chuck Pool	Owner (Pool Engineer)	907-225-6684	Off-site
John Pool	Forman (Pool Engineer)	907-617-1615	On-site

**FIELD ACTIVITIES**

Pool Engineers began mobilization to Knudson Cove.  
 Pool placed sections of the headwalk float in the water at Northland Service.  
 There was no damaged noted to the floats at this time.

\*PHOTOS TAKEN\*

CONSTRUCTION INSPECTOR Lance Greer DATE January 21, 2009



Photograph No. 1

**Description:**

Shipping company placing a section of the headwalk float into the water.