

# CONSTRUCTION INSPECTION REPORT

<b>Project: Knudson Cove Harbor</b>	<b>Report No: KCH 03</b>
<b>File No : 062010.05</b>	<b>Date: January 30, 2009</b>
<b>Consultant: PND Engineers, Inc.</b>	<b>Day of the Week: Friday</b>

<b>WEATHER</b>	Bright Sun	Clear	Overcast	Rain <input checked="" type="checkbox"/>	Snow	Other
<b>TEMP</b>	Below 0	0-32 <input checked="" type="checkbox"/>	32-50	50-70	70-85	Over 85
<b>WIND</b>	Still	Mod <input checked="" type="checkbox"/>	High	<b>Comments:</b>		
<b>HUMIDITY</b>	Dry	Mod <input checked="" type="checkbox"/>	Humid	<b>Comments:</b>		

<u>Name of Contractor</u>	<u>Non-Manual</u>	<u>Manual</u>	<u>Remarks</u>
Pool Engineer		5	

**CONTACTS**

<u>Name</u>	<u>Title</u>	<u>Phone No.</u>	<u>Remarks</u>
Chuck Pool	Owner (Pool Engineer)	907-225-6684	Off-site
John Pool	Forman (Pool Engineer)	907-617-1615	On-site

**FIELD ACTIVITIES**

Contractor continued placing stringers on the approach dock. They also removed existing approach wood piles. Existing wood piles were observed to be completely removed and placed on the Contractor's barge for disposal.

\*PHOTOS TAKEN\*

CONSTRUCTION INSPECTOR Lance Greer DATE January 30, 2009



Photograph No. 1

**Description:**

Existing approach piles being removed.