



Photo #1: Exterior deck demolition - stockpiled construction debris. Photo taken 11/10/08.



Photo #2: Roof replacement at Building 411. Photo taken 11/21/08.



Photo #3: New asphalt shingle roof at Building 411. Photo taken 12/14/08.



Photo #4: New energy efficient windows and exterior insulation at Building 411. Photo taken 01/14/09.



Photo #5: Roof replacement at Building 415. Photo taken 01/14/09.



Photo #6: Ongoing roof replacement at Building 414 Community Room. Photo taken 01/14/08.